## **HS-AS Studs**

adapters



Adapters to connect accelerometers to machine faces.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2			
HS-AS006	Quick Fit Female	1/4"-28 UNF Male			
113-A3000	Quick Fit Female	74 -20 ONI Wale			
HS-AS009	M6 Female	M8 Male			
	40.00 UNE M. I				
HS-AS026	10-32 UNF Male	M6 Male			
HS-AS028	Quick Fit Female ½" UNC	1/4"-28 UNF Male			
HS-AS030	M8 x 1.25 Female	1/8"BSPT Male			
HS-AS032	Quick Fit Female	M8 Male			
HS-AS039	Quick Fit Female ½" UNC	10-32 UNF Male		6	
HS-AS045	Quick Fit Female	M5 Female	•		
110 7.0040	Quick Fit Female	Wo I citate			
HS-AS088	Quick Fit Female 9/16" UNC	M5 Female		•	
110 40000	0/0" HNF F	0/0" NDT M-1-			
HS-AS092	3/8" UNF Female	3/8" NPT Male			
HS-AS103	1/4"-28 UNF Female	1/4" NPT Male	2000		
HS-AS107-M6	M6 Female	M6 Male			
HS-AS111	M8 Female	M8 Female		(3)	
HS-AS119	1/4"-28 UNF Female	1/4"-28UNF Male			
HS-AS121	1/4"-28 UNF Female	3/8"-16 UNC Male	•		
110 710 121	74 20 0141 1 0111dio	o.o To orto Maio			



www.hansfordsensors.com sales@hansfordsensors.com

