


AC acceleration and temperature output via Braided Cable



A diagram showing a circular sensor with three wires extending from it. The wires are labeled: a white wire for '+ve Power', a red wire for '+ve Temp.', and a black wire for '0V'. An arrow points to the outer casing of the sensor, labeled 'Screen to case'.

CE
UK
CA