# **HS-107T Accelerometer**

## AC acceleration and temperature output via M12 Connector


### **Key Features**

- · Line drive
- · Temperature output
- · For use with data collector

#### Industries

Building services, Pulp and Paper, Mining, Metals, Utilities, Automotive, Water, Pharmaceutical





Connection Details

### **Technical Performance**

Mounted Base Resonance see 'How To Order' table (nominal) Sensitivity see: 'How To Order' table ±10% Nominal 80Hz at 72°F Frequency Response 120cpm (2Hz) to 600kcpm (10kHz) ± 5% 90cpm (1.5Hz) to 720kcpm (12kHz) ± 10% 48cpm (0.8Hz) to 900kcpm (15kHz) ± 3dB Isolation Base isolated see: 'How To Order' table Range Temperature Output 10 mV/°C standard 212°F - Option 284°F Transverse Sensitivity Less than 5%

### Mechanical

Case Material Stainless Steel
Sensing Element/Construction PZT/Compression
Mounting Torque 5.9ft. lbs
Weight 3.7 oz. (nominal) body only
Sheilded Cable Assembly HS-AC010 - straight
HS-AC011 - right angle
Mounting Threads see: 'How To Order' table

## Electrical

 Electrical Noise
 0.1mg max

 Supply Voltage
 7.5 - 24Volts DC

 Bias Current
 3.5mA

 Settling Time
 2 seconds

 Output Impedance
 200 Ohms max

 Case Isolation
 >108 Ohms at 500 Volts

#### Environmental


 Operating Temperature Range
 -67 to 284°F

 Sealing
 IP67

 Maximum Shock
 5000g

 EMC
 EN61326-1:2013

### Typical Frequency Response




#### **Applications**

Fans, Motors, Pumps, Compressors, Centrifuges, Conveyors, Air Handlers, Gearboxes, Rolls, Dryers, Presses, Cooling, VAC, Spindles, Machine Tooling, Process Equipment

Vibration sensor should be firmly fixed to a flat surface (spot face surface may be needed to be produced and cable anchored to sensor body.)



## How To Order





www.hansfordsensors.com sales@hansfordsensors.com

