HS-183 Premium Triaxial Accelerometer

Three AC outputs via M12 Connector

Key Features

- Output via three axes
- · Three way mounting option
- · Customizable features

Industries


Building services, Pulp and Paper, Mining, Metals, Utilities, Automotive, Water, Pharmaceutical



see 'How To Order' table (nominal)

see: 'How To Order' table ±10%

Nominal 80Hz at 72°F per axies



Technical Performance

Mounted Base Resonance Sensitivity

120cpm (2Hz) to 600kcpm (10kHz) ± 5% Frequency Response 90cpm (1.5Hz) to 720kcpm (12kHz) ± 10% 48cpm (0.8Hz) to 900kcpm (15kHz) ± 3dB

Isolation Base isolated see: 'How To Order' table Range Transverse Sensitivity Less than 5%

Mechanical

Case Material Stainless Steel Sensing Element/Construction PZT/Shear Mounting Torque Mounting Bolt Provided see: 'How To Order' table x 1.2in long 8.3 oz. (nominal) - Stainless Steel HS-AC010 - straight Screened cable assembly Mounting Threads see: 'How To Order' table


Electrical

Electrical Noise 0.1mg max Current Range 0.5mA to 8mA Bias Voltage 10 - 12 Volts DC Settling Time 1 second Output Impedance 200 Ohms max. Case Isolation >108 Ohms at 500 Volts

Environmental

-67 to 300°F Operating Temperature Range Sealing IP67 Maximum Shock 5000g **EMC** EN61326-1:2013

Typical Frequency Response (at 100mV/g)




Applications

Fans, Motors, Pumps, Compressors, Centrifuges, Conveyors, Air Handlers, Gearboxes, Rolls, Dryers, Presses, Cooling, VAC, Spindles, Machine Tooling, Process Equipment

Vibration sensor should be firmly fixed to a flat surface (spot face surface may be needed to be produced and cable anchored to sensor body.)



How To Order





www.hansfordsensors.com sales@hansfordsensors.com

