HS-420ST Accelerometer

4-20mA velocity and temperature output via M12 Connector

Key Features


- · For use with PLC/DCS systems
- Temperature output


Industries

Building services, Pulp and Paper, Mining, Metals, Utilities, Automotive, Water, Pharmaceutical



Less than 5%





Technical Performance

Mounted Base Resonance 5kHz min

Velocity Ranges see: 'How To Order' table ±10%

Nominal 80Hz at 72°C

Frequency Response 600cpm (10Hz) to 60kcpm (1kHz) ± 5% - ISO10816

Isolation Base isolated

Range 50g peak

Temperature Output 10mV/°C - 0-1V proportional to 32-212°F (to convert this to 4-20mA use the HS-540 module)

Mechanical

Case Material Stainless Steel
Sensing Element/Construction PZT/Shear
Mounting Torque 5.9ft. Ibs
Mounting Bolt Provided see: 'How To Order' table x 1.2in long
Weight 6.5 oz. (nominal) body only
Sheilded Cable Assembly HS-AC010 - straight
HS-AC011 - right angle
Mounting Threads see: 'How To Order' table

Electrical

Transverse Sensitivity

Current Output 4-20mA DC proportional to Velocity Range
Supply Voltage 15-30 Volts DC (for 4-20mA)
Settling Time 1 second
Output Impedance Loop Resistance 600 Ohms max. at 24 Volts
Case Isolation >108 Ohms at 500 Volts

Environmental


 Operating Temperature Range
 -13 to 194°F

 Sealing
 IP67

 Maximum Shock
 5000g

 EMC
 EN61326-1:2013


Typical Frequency Response




Applications

Fans, Motors, Pumps, Compressors, Centrifuges, Conveyors, Air Handlers, Gearboxes, Rolls, Dryers, Presses, Cooling, VAC, Spindles, Machine Tooling, Process Equipment

Vibration sensor should be firmly fixed to a flat surface (spot face surface may be needed to be produced and cable anchored to sensor body.)



How To Order





www.hansfordsensors.com sales@hansfordsensors.com

