

## **Connection Details of Cable Assembly**



Connection Details	
Pin 1	Z Axis Signal (NC)
Pin 2	Y Axis Signal
Pin 3	Shield (NC)
Pin 4	X Axis Signal (NC)
Pin 5	-ve (0 volts)





Tel: +44(0) 845 680 1957 Fax: +44(0) 845 680 1958

Email: sales@hansfordsensors.com
Web: www.hansfordsensors.com