



EYE PROTECTION SHOULD BE WORN WHEN USING THIS PRODUCT




Hansford Sensors Excellence in Vibration Monitoring	
SPOT FACE KIT	
USER GUIDE LINE	
MANUAL	
QM028	lssue 1.1
Hansford Sensors	


Typical mounting position











Drilling detail examples














Z/Eng/Manuals/QM028