## HS-AS Studs Quick Fit threads



For use with accelerometers with quick-fit threads.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

HS-AS001 Quick Fit Male Glue Face	
HS-AS002 Quick Fit Male M8 Male	
HS-AS003 Quick Fit Male M6 Male	
HS-AS004 Quick Fit Male 1/4"-28 UNF Male	
	<u> </u>
HS-AS007 Quick Fit Male M10 Male	
HS-AS010 Quick Fit Male M8 x 1.25 Female	
HS-AS011 Quick Fit Male M6 x 1 Female	
3	
HS-AS012 Quick Fit Male 1/4"-28 UNF Female	
HS-AS013 Quick Fit Male (9/16" UNC) Glue Face	
HS-AS018 Quick Fit Male (1/2" UNC) Glue Face	



sales@hansfordsensors.com
We reserve the right to alter the specification of this product without prior notice
TS100.7

www.hansfordsensors.com



## HS-AS Studs Quick Fit threads

Part No. **Connection Point 1 Connection Point 2** 

HS-AS033	Quick Fit Male	M8 x 1 Male		
HS-AS034	Quick Fit Male (½" UNC)	M6 x 1 Male	P	
HS-AS037	Quick Fit Male (½" UNC)	M8 x 1.25 Male		
HS-AS041	Quick Fit Male	3/8" BSP	P	C.
HS-AS049	Quick Fit Male	1/8" BSP		
HS-AS064	Quick Fit Male	M5 Male		8
HS-AS065	Quick Fit Male	Glue face and M6 x 1 Female		
		M8 x 8mm Male		8
HS-AS072	Quick Fit Male			E
HS-AS078	Quick Fit Male	Glue Face in 316L Stainless Steel		
HS-AS108	Quick Fit Male	M12 Male	5	Contraction of the second seco
HS-AS120	Quick Fit Male	1/4"NPT Male		
				C



www.hansfordsensors.com sales@hansfordsensors.com

