HS-AS Studs

Quick Fit threads



For use with accelerometers with quick-fit threads.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2		
HS-AS001	Quick Fit Male	Glue Face		
				4
HS-AS002	Quick Fit Male	M8 Male		
HS-AS003	Quick Fit Male	M6 Male		
HS-AS004	Quick Fit Male	1/4"-28 UNF Male		
				<u></u>
HS-AS007	Quick Fit Male	M10 Male		
			(4)	
HS-AS010	Quick Fit Male	M8 x 1.25 Female		
HS-AS011	Quick Fit Male	M6 x 1 Female		
			3	
HS-AS012	Quick Fit Male	1/4"-28 UNF Female		
HS-AS013	Quick Fit Male (9/16" UNC)	Glue Face		
HS-AS018	Quick Fit Male (½" UNC)	Glue Face		







HS-AS Studs Quick Fit threads

Pa	rt No.	Connection Point 1	Connection Point 2		
HS-	AS033	Quick Fit Male	M8 x 1 Male		
HS-	AS034	Quick Fit Male (½" UNC)	M6 x 1 Male		
					•
HS-	AS037	Quick Fit Male (½" UNC)	M8 x 1.25 Male		
HS-	AS041	Quick Fit Male	3/8" BSP		
HS-	AS049	Quick Fit Male	1/8" BSP		
HS-	AS064	Quick Fit Male	M5 Male		
HS-	AS065	Quick Fit Male	Glue face and M6 x 1 Female		
					6
HS-	AS072	Quick Fit Male	M8 x 8mm Male		
HS-	AS078	Quick Fit Male	Glue Face in 316L Stainless Steel		
HS-	AS108	Quick Fit Male	M12 Male	5	
HS-	AS120	Quick Fit Male	1/4"NPT Male		
					6





