## HS-AA069 3 Pin MS connector with Boot





We manufacture a range of accessories for use with our comprehensive series of industrial accelerometers.

The 3 Pin MS connector with rubber boot for cables ø4.2 connection details. These connectors are for use in cable assemblies.


## **Product Description**

## **Front View**





## How To Order





www.hansfordsensors.com sales@hansfordsensors.com

