



6 Pin Fischer Plug: Pin 1 - Brown (X-Axis) - M12 Socket: Pin 1,
6 Pin Fischer Plug: Pin 2 - White (Y-Axis)- M12 Socket: Pin 2,
6 Pin Fischer Plug: Pin 6 - Blue (Z-Axis)- M12 Socket: Pin 3,
6 Pin Fischer Plug: Pin 5 - Black & Drain (0V Common) - M12 Socket: Pin 4, Case -Braided Screen.

Front view of
4 Pin M12 Connector





Brown core
White core
Screen
Blue Core
Black Core

Front view of
6 Pin Fischer Connector



4 Pin M12 Connector



6 Pin Fischer Plug


Rev No	DRF No	Date Drg	Drg By	Appd By
A	Release	24/11/15	MJS	SRB

Material: N/A	
Tolerances Unless Stated	
0 or 0.0	±0.5
0.00	±0.15
Angle	±5°
1.6/ Finish All Over Threads g6 H6	



Hansford Sensors
Excellence in Vibration Monitoring

Hansford Sensors Ltd
Artisan, Hillbottom Road
Sands Industrial Estate
High Wycombe
Bucks HP12 4HJ



Do Not Scale

**All Dimensions In mm Unless
Otherwise Stated**

If In Doubt - Ask!

Description: SKF AX/GX Data Collector
Cable F.U.W HS-173 Triaxial Sensor

Drawing No: HS-AC578

Scale: 2 : 1

Form Number: QF024 Issue 3

Sheet: 1 of 1