HS-100S Accelerometer

AC acceleration output via M12 Connector


Key Features


- · For use with data collector
- · Side entry for easy access
- · Customisable features

Industries

Building services, Pulp and Paper, Mining, Metals, Utilities, Automotive, Water, Pharmaceutical







Technical Performance

Mounted Base Resonance see 'How To Order' table (nominal)
Sensitivity see: 'How To Order' table ±10%
Nominal 80Hz at 22°C
Frequency Response 2Hz (120cpm) to 10kHz (600kcpm) ± 5%
1.5Hz (90cpm) to 12kHz (720kcpm) ± 10%
0.8Hz (48cpm) to 15kHz (900kcpm) ± 3dB
Isolation Base isolated
Range see: 'How To Order' table
Transverse Sensitivity Less than 5%

Mechanical

Stainless Steel Case Material Sensing Element/Construction PZT/Compression Mounting Torque 8Nm Mounting Bolt provided see: 'How To Order' table x 35mm long Weight 205gms (nominal) body only Maximum Cable Length n/a Standard Cable Length n/a Screened Cable n/a Screened Cable Assembly see: www.hansfordsensors.com for options Connector HS-AC010 - straight or HS-AC011 - right angle Mounting Threads see: 'How To Order' table Submersible Depth n/a

Electrical

 Excitation Voltage:
 18-30Volts DC

 Electrical Noise
 0.1mg max

 Current Range
 0.5mA to 8mA

 Bias Voltage
 10 - 12 Volts DC

 Settling Time
 2 seconds

 Output Impedance
 200 Ohms max

 Case Isolation
 >10^8 Ohms at 500 Volts

Environmental


 Operating Temperature Range
 -55 to 140°C

 Sealing
 IP67

 Maximum Shock
 5000g

 EMC
 EN61326-1:2013

Typical Frequency Response (at 100mV/g)



Applications

Fans, Motors, Pumps, Compressors, Centrifuges, Conveyors, Air Handlers, Gearboxes, Rolls, Dryers, Presses, Cooling, VAC, Spindles, Machine Tooling, Process Equipment

Vibration sensor should be firmly fixed to a flat surface (spot face surface may be needed to be produced and cable anchored to sensor body).



How To Order

